




DRAFT



CURRENT CONDITIONS REPORT FOR THE SAGINAW RIVER, FLOODPLAIN, AND BAY

Prepared for
THE DOW CHEMICAL COMPANY

Prepared by
ENVIRON

14 September 2007

A P P E N D I X A

Photographic Log of Saginaw River



Photo 1: Armored river bank in Bay City, MI



Photo 2: Wastewater treatment plant outfall near Bay City, MI

Title:	Appendix A: Ecological Site Visit Photographs	Date : June 26, 2007
Site:	Saginaw River, Michigan	Project-No.: 0318007A
Client:	The Dow Chemical Company	ENVIRON



Photo 3: Riparian vegetation along Saginaw River in Bay City, MI



Photo 4: Middleground Island, Bay City, MI

Title:	Appendix A: Ecological Site Visit Photographs	Date : June 26, 2007
Site:	Saginaw River, Michigan	Project-No.: 0318007A
Client:	The Dow Chemical Company	ENVIRON



Photo 5: Landfill near Bay City, MI



Photo 6: Riparian vegetation between Bay City and Saginaw, MI

Title:	Appendix A: Ecological Site Visit Photographs	Date : June 26, 2007
Site:	Saginaw River, Michigan	Project-No.: 0318007A
Client:	The Dow Chemical Company	ENVIRON



Photo 7: Residential development near Saginaw, MI



Photo 8: Bridges in Saginaw, MI

Title:	Appendix A: Ecological Site Visit Photographs	Date : June 26, 2007
Site:	Saginaw River, Michigan	Project-No.: 0318007A
Client:	The Dow Chemical Company	ENVIRON



Photo 9: Gravel yards adjacent to the Saginaw River, near Saginaw, MI



Photo 10: Armored bank and outfall in Saginaw, MI

Title:	Appendix A: Ecological Site Visit Photographs	Date : June 26, 2007
Site:	Saginaw River, Michigan	Project-No.: 0318007A
Client:	The Dow Chemical Company	ENVIRON



Photo 11: The confluence of the Shiawassee (left) and Tittabawassee (right) Rivers forming the Saginaw River near Saginaw MI

Title:	Appendix A: Ecological Site Visit Photographs	Date : June 26, 2007
Site:	Saginaw River, Michigan	Project-No.: 0318007A
Client:	The Dow Chemical Company	ENVIRON